

Small House
(Kingsway Center Commercial Area)
1337 Euclid Avenue
St. Louis
St. Louis County
Missouri

HABS No. MO-60-L

HABS
MO,
96-SALV,
133-L-

PHOTOGRAPHS



WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Rocky Mountain Regional Office
Department of the Interior
P.O. Box 25287
Denver, Colorado 80225

NATIONAL PARK SERVICE
ROCKY MOUNTAIN REGION



ARCHITECTURAL DATA FORM

STATE MISSOURI	COUNTY	TOWN OR VICINITY CITY OF SAINT LOUIS
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Small House (Permits)		EABS NO. MO-60-L
SECONDARY OR COMMON NAMES OF STRUCTURE		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 1337 Euclid Avenue		
DATE OF CONSTRUCTION (INCLUDE SOURCE) 1892 (Permits)	ARCHITECT(S) (INCLUDE SOURCE) L. Silva-owner (Permits)	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The Kingsway Center Area is locally significant for its architectural significance as an important representative illustration of neighborhood development and urban vernacular building traditions in late 19th-century St. Louis. The Small House is one of the structures in the area that contributes to a potential historic district. Original Use: single-family residence.		
STYLE (IF APPROPRIATE) Queen Anne		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Cut stone/masonry foundation. Partial basement w/concrete floor, crawl area. Brick & concrete block walls. Masonry building frame. Galvanized gutters & downspouts. Roof: Part hip/asphalt single; part flat w/9016 roll roofing. Hardwood floors. Plaster wallpaper & wood panel walls. acoustic tile & plaster ceilings. Cast iron & galvanized plumbing. Gas heating, gravity furnace. Incandescent lighting 100 amp fuse box. 40 gal. gas water heater.		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE SHEETS ARE ACCEPTABLE) Floor Plan Attached		
EXTERIOR FEATURES OF NOTE This building has a projecting gable with masonry coping & roll moulding & a gable windows w/ a segmental arch. It has a dormer with a hipped head & wood grained lights. There is a raised brick entablature at the roof line. It has a single door with a leaded side light. The first floor has a large round arched window with roll moulding at the impost and overhang. It also has masonry sills with ovolo mouldings.		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Floor plan attached.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES The only major alteration reflected in the available building permits was undertaken in April, 1954. However, the nature & extent of these improvements is unclear because the description contained in the permit simply states that alterations were made. Based on inspection of the building this may have involved the construction of a rear addition & adding awning to the front porch & all front windows.		
PRESENT CONDITION AND USE Good condition - Single Family Residence		
OTHER INFORMATION AS APPROPRIATE L. Silva owned this parcel and constructed the building. Mr. & Mrs. Small purchased the property and were the first occupants.		
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Building Division of the City of St. Louis. Records of the City Assessor. Appraisal report-Real Estate Analysts, Ltd. Report of Cultural Resource Assessment-Archaeological Survey, University of Missouri-St. Louis. Gould's City Directory/Blue Book, 1893, 1896, 1897, and 1898. Notification from the Keeper of the National Register and the Missouri Historic Preservation Program.		
COMPILER, AFFILIATION City of St. Louis, Project Manager		DATE July 18, 1986





SMALL HOUSE
1337 Euclid Ave
St. Louis, MO
August 4, 1986

1ST FLOOR



SMALL HOUSE
1337 Euclid Ave
St. Louis, MO
August 4, 1986

2ND FLOOR



SMALL HOUSE
1337 N. Euclid Ave
St. Louis, MO
August 4, 1986

ATTIC